



Acoustic Resonance in Nuclear Boiling Water Reactors


Thomas G. Scarbrough
Division of Engineering
Office of New Reactors
U.S. Nuclear Regulatory Commission

Pennsylvania State University
Center for Acoustics and Vibration Workshop
April 29-30, 2013


Introduction

- Some nuclear power plants with boiling water reactors (BWRs) have experienced significant acoustic resonance in their reactor and steam systems.
- In some cases, acoustic resonance has resulted in damage to plant components in reactor pressure vessel (RPV) and steam lines.
- As a result, nuclear power plant applicants and licensees evaluate potential adverse flow effects during initial plant design and startup of new reactors, and for power uprates of operating reactors.

Boiling Water Reactor



Boiling Water Reactor Pressure Vessel




Acoustic Resonance

- Turbulent steam flow in RPV can excite large-scale, low-frequency acoustic modes
- Steam flow over safety valves (SVs), safety relief valves (SRVs), and other branch lines can couple with high-frequency acoustic mode of branch steam column
- Pressure fluctuations with low and high frequencies in RPV and steam lines can impact steam dryer
- Acoustic resonance has caused severe vibration of steam line components



Strouhal Analysis

- Strouhal number can be defined as fD/U , where f is frequency at which shear layer oscillates, D is side-branch opening diameter, and U is steady flow speed of shear layer
- Strouhal numbers can vary with pipe diameter ratio, distance from upstream elbows, and acoustic damping
- Strouhal number chart developed by Ziada and Shine to predict critical flow velocity at which acoustic resonances may be initiated

Valve Tone Excitation in BWR Steam Lines




“Singing” Safety Relief Valve



U.S. BWR Unit 2 Steam Dryer Experience

- In June 2002, steam dryer cover plate failed after 90 days of power uprate operation (117% original power).
- In June 2003, steam dryer hood failed after additional 300 days of power uprate operation.
- In March 2004, steam dryer cracked after additional 8 months of power uprate operation.


BWR Unit 2 Steam Dryer Failures (2002 and 2003)



U.S. BWR Unit 1 Steam Dryer Experience

- In November 2003, steam dryer hood failed after 1 year of power uprate operation (117% original power).
- 6x9 inch plate of steam dryer outer bank lost in reactor coolant and steam system
- Damage also found to steam line components

BWR Unit 1 Steam Dryer Failure (Nov. 2003)





270° Side



Example BWR Steam Dryer Replacement

- In Spring 2005, BWR Units 1 and 2 steam dryers replaced with improved design
- Unit 2 steam dryer instrumented with pressure sensors, strain gages, and accelerometers
- BWR steam lines instrumented with strain gages to calculate pressure load on Unit 1 steam dryer based on Unit 2 benchmark
- Highest pressure load of $0.65 \text{ psi}^2/\text{Hz}$ (168 dB) on steam dryer during BWR power uprate operation



BWR Unit 2 Replacement Steam Dryer



BWR Unit 2 Steam Dryer Pressure Spectral Densities (790 MWe Original Licensed Power Level)



BWR Unit 2 Steam Dryer Pressure Spectral Densities (930 MWe Power Uprate Power Level)



Safety Relief Valve Damage

- In late 2005, SRV in BWR Unit 2 experienced short circuiting
- Unit 2 reduced power for inspection with broken SRV actuator parts found
- Both BWR units shut down for inspection with damage found to several SRVs
- SRV damage caused by severe vibration from acoustic resonance
- As a result, licensee initiated program to eliminate acoustic resonance from BWR steam lines

BWR Acoustic Resonance Elimination

- Analysis indicated that SV and SRV branch line length could not be reduced sufficiently to cause acoustic resonance to occur at steam velocity beyond operating conditions
- Licensee installed deadleg T-connection pipe in SV and SRV branch lines to effectively lengthen branch line and cause acoustic resonance to occur at lower steam velocity with reduced pressure fluctuations
- Upon reactor restart, measurements indicated significant acoustic resonance sources eliminated

Acoustic Resonance Lessons Learned

- NRC Regulatory Guide 1.20 revised to provide guidance on potential adverse flow effects
- Operating BWRs proposing power uprate and new BWR applications evaluate potential adverse flow effects from acoustic resonance
- Vendors have developed proprietary methods using data from replacement steam dryers and steam lines to determine pressure load and stress on steam dryers
- BWR licensees monitor steam dryer and steam line data during power ascension and implement steam dryer inspection program during refueling outages

References

- S.A. Hambric, et al., “Flow-Induced Vibration Effects on Nuclear Power Plant Components Due to Main Steam Line Valve Singing,” U.S. NRC NUREG/CP-0152, Volume 6, Proceedings of the Ninth NRC/ASME Symposium on Valves, Pumps and Inservice Testing, 2006.
- G. DeBoo, et al., “Identification of Quad Cites Main Steam Line Acoustic Sources and Vibration Reduction,” 2007 ASME Pressure Vessels and Piping Division Conference, Proceedings of PVP2007, July 2007.
- S. Ziada, “Flow-Excited Acoustic Resonance in Industry,” Institute of Thermomechanics, Flow Induced Vibration, Zolotarev & Horacek, eds., Prague, 2008.